Order No.	Model	Description
005 61 046 99	**W 101**	**Line voltage soldering iron 100 W, 230 V, Magnastat controlled** • complete with soldering tip CT6 E7 and safety rest

Soldering Tips for W 101

Order No.	Model	Description	Width A
4CT6C7	**CT6 C7**	Chisel tip 370°C	3,2 mm
4CT6C8	**CT6 C8**	Chisel tip 425°C	3,2 mm
4CT6D7	**CT6 D7**	Chisel tip 370°C	5,0 mm
4CT6D8	**CT6 D8**	Chisel tip 425°C	5,0 mm
4CT6E7	**CT6 E7**	Chisel tip 370°C	7,0 mm
4CT6E8	**CT6 E8**	Chisel tip 425°C	7,0 mm



005 42 307 99	**CT6 CX7**	Chisel tip bent 370°C	3,2 mm
005 42 318 99	**CT6 DX8**	Chisel tip bent 425°C	5,0 mm

Adapter to use LH-Tip series (page 87) with W 101

Order No.	Model	Description
005 61 046 67	**CT6-7**	Adapter for LHT tips, 370°
005 61 046 68	**CT6-8**	Adapter for LHT tips, 425°
005 61 046 69	**CT6-9**	Adapter for LHT tips, 480°

Soldering Iron W 101SP with Twist Lock

Order No.	Model	Description
005 61 096 99	**W 101SP**	**Line voltage soldering iron 100 W, 230 V, Magnastat controlled with twist lock (260°C–295°C)** • complete with welding wedge Teflon coated, 50 x 40 x 4 mm and safety rest

Soldering Tips

Order No.	Description
005 11 767 99	Welding wedge Teflon coated, 50 x 40 x 4 mm (260°C–295°C) for W 101SP with Twist Lock
005 11 767 74	Welding wedge PTFE coated, 50 x 40 x 4 mm for W 201 iron (260°C–295°C) without Twist Lock